Newport Harbour - outstanding PMSC audit actions - Version 1.16; 24.08.2022																										
Items from PMSC audit, November 2020							Nov-21	Dec-21	Jan-22	Feb-22	Mar-22	Apr-22	May-22	Jul-22	A119-22	Sep-22	Oct-22	Nov-22	Dec-22	Jan-23	Feb-23	Mar-23 Apr-23	Apr-23 May-23	Jun-23	Jul-23	Aug-23 Sep-23
No.	Action	Sub action	By Who	By When	Comments																					
А	Navigational risk assessment	It is recommended that the NRA is reviewed at least once a year or as a follow-up of any incident investigation.	JB	Sep-22	Review delayed to resource implications arising from Covid-19																					
С	Commercial berth operators	The commercial berth operators procedures for mooring commercial vessels are reviewed ensuring mooring gangs are trained correctly and that self-mooring is prohibited.	JB	Sep-22	See MAIB Report 9/2020 and Port Skills and Safety - Spotlight on Self Mooring Fatalities.																					
Additional items from PMSC audit, October 2021								ec-21	an-22	eb-22	1ar-22	4pr-22	May-22	ul-22	27-011	ep-22	Oct-22	Nov-22	)ec-22	an-23	eb-23	Mar-23 Apr-23	/pr-23	un-23	lul-23	Aug-23 Sep-23
No.	Action	Sub action	By Who	By When	Comments	Oct-21	Nov-21		Ϋ́	Ľ.	2	<u>∢ </u> '	<u> </u>	45		Š		2		Š	ه کا	_	+=	占	15	A S
A1	Consultation and Communication	It is recommended that a new Marine Safety Management Plan is drafted for approval	JB	Aug-22																				Ι		
А3	Risk Assessment	It is recommended that the top hazards listed in the NRA are regularly included in reports to the Duty Holder;	JB	Ongoing	These will be included in the quarterly reports to the harbour committee																					
A4	Marine Safety Management System	The current version of the Marine Safety Management System (MSMS) is in need of review and update including to reflect the new HRO;	JB	Aug-22																						
A5	Marine Safety Management System	It is recommended that the MSMS incident recording, investigation monitoring and after actions guidance is reviewed, developed and put in one place within the MSMS	JB	Aug-22																						
А7	Marine Services	It is recommended that the commercial berth operators' procedures for the mooring of commercial vessels are reviewed ensuring mooring gangs are trained correctly and that self-mooring is prohibited	JB	Aug-22																						
А9	Professional Qualification and Competencies	It is recommended that the personal qualification and training records of the Senior Harbour Master's staff in the MSMS are reviewed to ensure that they are up to date;	JB	Aug-22																						